# Oil Field Environmental Incident Summary

**Responsible Party:** CORINTHIAN EXPLORATION (USA) CORP **Well Operator:** CORINTHIAN EXPLORATION (USA) CORP

Well Name: CORINTHIAN LOCHNER 16-33 1-H

Field Name: NORTH SOURIS Well File #: 26714

Date Incident: 5/5/2014 Time Incident: 14:00 Facility ID Number:

County: BOTTINEAU Twp: 164 Rng: 77 Sec: 33 Qtr: SE SE

Location Description: A pipeline failure was observed by a Corinthian field pumper on the edge of

the Lochner 16-33 lease. The emulsion from the pipeline leaked onto the

North end of the lease and down the hill into the landowner's field.

Submitted By: Patrick Gratton Received By:

Contact Person: Patrick Gratton

STE 230, 323-10TH AVE SW CALGARY, AB T2R 0A5

General Land Use: Pasture Affected Medium: Topsoil

Distance Nearest Occupied Building:0.8 MileDistance Nearest Water Well:0.8 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units
Oil 3 Barrels 3 Barrels
Brine 17 Barrels 17 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Soil contamination from the produced fluids.

Areal Extent:

Approximately 500 square yards

**Followup** 

Units

### Potential Environmental Impacts:

The topsoil of the farmers field was contaminated with produced water and requires to be disposed of at a waste facility. The land will be reclaimed with fresh topsoil.

#### Action Taken or Planned:

The local NDIC field inspector was notified of the spill and has visited the site. The line will have a full failure diagnosis with implementation of new installation design and procedures to prevent a repeat line failure.

Wastes Disposal Location: All contaminated soil will be taken to the Clean Harbors Sawyer Waste Facility for disposal. Fresh top soil will fill any removed contaminated area.

Agencies Involved:

## **Updates**

Date: 5/6/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

An on-location pipeline leak flowed off location into an agricultural field. Followup is necessary. Sampling of soil from 0-6, 6-12, and 12-24 inches in the impact area for sodium, chloride, SAR, and ESP is required.

Date: 5/14/2014 Status: Inspection Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Arrived on location on 5/14/14.

Remediation is currently in progress. There are signs of crude oil in the area. The spill occurred at the top of the hill near the well pad and ran down the hill. The impacted material has been scraped up.

More followup is necessary to ensure cleanup.

Date: 6/9/2014 Status: Inspection Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Arrived on location 6/9/14.

Removal of impacted soil is complete. Only leveling and reseeding of native grasses remains to be done at the site.

More followup is necessary.

Date: 8/25/2014 Status: Inspection Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Arrived on location 8/25/2014.

Area has been reseeded and is recovering nicely.

No more followup is necessary.